

ATTACHMENT "D" – PROJECT LOCATION MAPS



Overall Map

Walleye Picnic Area




Site B2

Former Swim Beach and Boat Ramp 2



SHORELINE EROSION AREAS

High Conflict Area (HCA): Area observed to have both a high physical and user risk



Not shown: Erosion at Copperas Branch Trail discovered after study; focus of temporary repairs under consideration by USACE

Focus of PSA being considered

focus of temporary repairs; currently under review by USACE